

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-006053**Date Inspected:** 30-Mar-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 645**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1845**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Liu Yang**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** TOWER COMPONENTS**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, Gady Rao, was present during the times noted above for observations relative to the work being performed.

Magnetic Particle Testing:

This QA inspector performed MT of approximately 15% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an MT report for this date. The member(s) & the weld designations reviewed are as follows:

Bay 10

Skin to Stiffener & Gusset plate; Lift – 2; North Tower ; Skin D.

Bay 10

SAW

1) SAW welding of weld joint SSD1–FCSA3–1B/C–57A located on PCMK LS3-59 to LS3-25; Lift–3. Welder is identified as 053673. ZPMC QC is identified as Zhong Huang / Liu Yang. The welding variables recorded by QC appeared to comply with the B–T–2221–B–U3C–S–2.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

2)SAW welding of weld joint SSD1-FDSA3-1B/C-24B,32A located on PCMK LS3-39 to LS3-59; LS3-55 to LS3-59 Lift-3. Welder is identified as 209051/053673. ZPMC QC is identified as Zhong Huang / Liu Yang. The welding variables recorded by QC appeared to comply with the B-T-2221-B-U3C-S-2.

SMAW

1)SMAW welding of welds joint ND1-A467-47.6M-4-69/70 located on PCMK P282 to P859;LIFT-3. Welders are identified as 040582. ZPMC QC is identified as Liu Yang. The welding variables recorded by QC appeared to comply with the B-T-2112.

2)SMAW welding of welds joint ND1-A467-77M-2-31A located on PCMK P234 to PA476;LIFT-3. Welders are identified as 040582. ZPMC QC is identified as Liu Yang. The welding variables recorded by QC appeared to comply with the B-T-2212-C-U5B.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

No relevant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Serge Sinevod 134-8257-0045., who represents the Office of Structural Materials for your project.

Inspected By:	Rao,Gady	Quality Assurance Inspector
Reviewed By:	Clifford,William	QA Reviewer
